

Georgia Power Company
333 Piedmont Avenue
Atlanta, Georgia 30308
Telephone 404 526-6526

Mailing Address
Post Office Box 4545
Atlanta, Georgia 30302

Power Generation Department

83 JAN 6 AM 45
December 30, 1982



U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II - Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30303

REFERENCE:
RII: RFR
Inspection Report
50-321/82-32
50-366/82-30

ATTENTION: Mr. James P. O'Reilly

GENTLEMEN:

The following is submitted as a supplemental response to our letter of November 30, 1982 concerning I&E Inspection Report 50-321/82-32 and 50-366/82-30.

As discussed in a telephone conversation with your staff on December 20, 1982 and following further investigation of the causes of Violation B, Item 1, it was revealed that non-licensed personnel at the Plant Hatch site did not follow procedure HNP-425 in that the identified deviation on the standby gas treatment system was not brought to the immediate attention of the shift supervisor. Our earlier response discussed the need to conduct an evaluation of deviations in general terms and the problems inherent with that process. However, the subject event and violation of 10 CFR 50.72a(5) occurred because a non-licensed person did not immediately report the deviation to the shift supervisor. Accordingly, the need to immediately report deviations of a safety nature to the shift supervisor will be emphasized to the person involved. The individual involved is a relatively new GPC employee, hired since the last training was given on this procedure. This action will be completed by January 15, 1983.

If you have further questions, please contact this office.

Very truly yours,

L. T. Guwa
Chief Nuclear Engineer

/mb

xc: J. T. Beckham, Jr.
Senior Resident Inspector
H. C. Nix, Jr.

8302150627 830119
PDR ADOCK 05000321
Q PDR