



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville South Carolina 29550

FEB 08 1983

Robinson File No: 13510C

Serial: RSEP/82-185

Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
LICENSEE EVENT UPDATE REPORT 81-27, REVISION 1

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit No. 2, the enclosed Licensee Event Report is submitted. The original Report, December 15, 1981, described seal failure on "A" Residual Heat Removal Pump and resultant leakage in excess of the amount specified in Technical Specification 4.4.3.a. The Report indicated that an investigation into the root cause of the problem, which was a purchase order error, was in progress, and any required corrective action would be reported. This Report provides the results of that investigation. This revision contains a complete description of the event with new information indicated by a vertical bar in the right hand margin. This Report, therefore, supersedes and should replace all copies of the original LER.

Very truly yours,

R. B. Starkey, Jr.
General Manager
H. B. Robinson S.E. Plant

HTC/tm

Enclosure

cc: R. A. Hartfield (3)
R. C. DeYoung (30)

8302150677 830208
PDR ADOCK 05000261
S PDR

OFFICIAL COPY

IE 22