




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BLAUMONT, TEXAS 77704

AREA CODE 713 838-6631

February 4, 1983
RBG-14,294
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-84

On December 6, 1982, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning a linear indication found in the root area of a fillet weld for a lug on one SRV quencher (DR-84). GSU has not completed its investigation at this time. An interim or final status report will be submitted by March 31, 1983.

Sincerely,

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)

IE 27