NRC FORM 366

U. S. NUCLEAR REGULATORY COMMISSION

(7-77)	LICENSEE EVENT REPORT
	CONTROL BLOCK:
01	M I P A L 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 5 5 CAT 58
CON'T	SOURCE L 6 15 10 10 12 15 5 0 01 11 0 8 13 8 0 12 10 8 8 3 9
0 2	During routine review of past snubber surveillances, some discrepancies were
0]3	Inoted in the 1981 results for Snubber No 63 (LPSI to T-82C). The snubber
04	was inspected, found to be inoperable, and replaced. Condition reportable
015	per TS 3.20.1 and 6.9.2.b(2).
0 6	
0 7	
018	
0 9	SYSTEM CAUSE SUBCODE COMPONENT CODE SUBCODE SU
	LER RO EVENT YEAR REPORT NO. 1) NO.
10	Because of a deficiency in the surveillance procedure, fluid was added to
111	Snubber No 63 during 1981 inspection and no further action was taken. On
112	1-12-83, Snubber No 63 was removed, tested, and found to have been able to
13	perform its intended function. The deficient surveillance procedure will be
114	revised to alleviate the identified problems.
1 5	ACTUTY POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA STATUS 30 NA STA
	ILEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) NA NA NA NA NA NA NA N
7 8	NUMBER TYPE DESCRIPTION (39) O O O 37 Z 38 NA PERSONNEL INJURIES 13 80
7 8	NUMBER DESCRIPTION (41) O O O O O D O O O D O O O O O O O O O
وآبا	Z 42 NA
	NAC USE ONLY NAC USE ONLY NAC USE ONLY
8302160 PDR ADO S	255 830208 CK 05000255 CK 05000255