

SEP 0 2 1982

Lindsay Wire Weaving Company
ATTN: Mr. Ellsworth H. Shriver
6151 Wilson Mills Road - Suite 200
Cleveland, Ohio 44143

License No. 34-20211-01

Gentlemen:


This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on July 2 and August 11, 1982, of activities authorized by NRC Byproduct Material License No. 34-20211-01 and to the telephone conversation concerning our inspection results with you on August 30, 1982.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

cc: DMB/Document Control Desk (RIDS)

RIII
WR
Reichhold/sv
9/1/82

RIII
for
Sreniawski
9/2/82

8209080436 820902
NMS LIC30
34-20211-01 PDR

IE - HQ File Copy
PMB IE-07