PILGRIM NUCLEAR POWER STATION RED #1 ROCKY HILL ROAD PLYMOUTH, MASSACHUSETTS 02360 August 13, 1982 R. D. MACHON DULLAR OPERATIONS MANAGER BECo Ltr. #82-210 PILONIM STRTION Ronald C. Haynes Regional Administrator, Region 1 U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406 Docket Number 50-293 License DPR-35 Dear Sir: The attached Licensee Event Report 82-022/03L-0 "Recirculation Pump - Speed Mismatch", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.b. This report is being processed within the time frame of a 24 hour report to bring it promptly to your attention since the time frame for remedial action has been raised as a critical issue. PNPS believes that existing station procedures and the actions taken to resolve this event were adequate, timely and within the intent of the Technical Specifications and CFR guidance; therefore this event more appropriately satisfies the reporting requirement specified in 6.9.B.2.b. If there are any questions on this subject, please contact us. Respectfully submitted, Nuclear Operations Manager Pilgrim Station GGW:ep Enclosure: LER 82-022/03L-0 cc: Document Control Desk U. S. Nuclear Regulatory Commission Washington, D.C. 20555 Standard BECo LER Distribution 8209130189 820813