

Appendix

NOTICE OF VIOLATION

Union Electric Company

Docket No. 50-483

As a result of the inspection conducted on July 21-31, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

10 CFR 50, Appendix B, Criterion V, Instructions, Procedures and Drawings, states, "Activities affecting quality shall be prescribed by documented instructions, procedures, or drawings...and shall be accomplished in accordance with these instructions, procedures or drawings."

Daniel International Corporation's Procedure QCP-307, Inspection of Electrical Seismic II/I Installations, Revision 0, dated 3-12-82, section 3.1 states, "The Project Electrical Engineer shall be responsible for ensuring that applicable Seismic II/I related material/equipment is installed in accordance with...this procedure." Section 3.2 of QCP-307 states, "Electrical Quality Control shall be responsible for inspection of Seismic II/I related materials and installations in accordance with this procedure...."


Contrary to the above, the junction box and hanger installation above Class IE conduit 4U1029 on the 1988 ft. elevation had not been installed or inspected according to procedures governing Seismic II/I installations.

This is a Severity Level V violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

August 25, 1982

Dated



R. L. Spessard, Director
Division of Project and
Resident Programs