

SEP 12 1983

MEMORANDUM FOR: Darrell G. Eisenhut, Director, Division of Licensing, NRR

FROM: Thomas T. Martin, Director, Division of Engineering and Technical Programs, RI


SUBJECT: ALLEGATIONS CONCERNING ADEQUACY OF STANDBY DIESEL GENERATORS AT NINE MILE POINT, UNIT 2

Attached is NRC Region I Inspection Report No. 50-410/83-06 conducted as a result of allegations received by Region I on April 22, 1983 (Allegation No. RI-83-A-0037). Although no immediate technical deficiencies were identified, the inspector identified several deficiencies in the information recently submitted to the NRC in Nine Mile Point, Unit 2's Final Safety Analysis Report. (See Sections 4.0 and 5.0 of the report). Also, it appears that the FSAR submittal does not conform completely with Standard Review Plan Section 8.3.1.

It is requested that the responsible project manager be made aware of the noted discrepancies in the FSAR. Note should also be taken of Section 3.3 of the inspection report which discusses deficiencies in the diesel generator qualification test program. We understand that the FSAR is currently under review.

If you have any questions, please contact Mr. Clifford Anderson of my staff. (FTS 488-1376)

Original Signed by
S. D. Ebner



Thomas T. Martin, Director
Division of Engineering and
Technical Programs

Attachment: As stated

- ccc
- cc w/attachment:
- M. Haughey, NRR
- D. Lazevnick, NRR
- C. Anderson, RI
- B. Gramm, RI

8310050072XA

F/5 62

OFFICE	PLISCO	CIA	GM	SE		
SURNAME	ANDERSON	MARTIN	EBNER			
DATE	9/7/83	9/7/83	9/8/83			

SEP 12 1983

MEMORANDUM FOR: Darrell G. Eisenhut, Director, Division of Licensing, NRR

FROM: Thomas T. Martin, Director, Division of Engineering and Technical Programs, RI


SUBJECT: ALLEGATIONS CONCERNING ADEQUACY OF STANDBY DIESEL GENERATORS AT NINE MILE POINT, UNIT 2

Attached is NRC Region I Inspection Report No. 50-410/83-06 conducted as a result of allegations received by Region I on April 22, 1983 (Allegation No. RI-83-A-0037). Although no immediate technical deficiencies were identified, the inspector identified several deficiencies in the information recently submitted to the NRC in Nine Mile Point, Unit 2's Final Safety Analysis Report. (See Sections 4.0 and 5.0 of the report). Also, it appears that the FSAR submittal does not conform completely with Standard Review Plan Section 8.3.1.

It is requested that the responsible project manager be made aware of the noted discrepancies in the FSAR. Note should also be taken of Section 3.3 of the inspection report which discusses deficiencies in the diesel generator qualification test program. We understand that the FSAR is currently under review.

If you have any questions, please contact Mr. Clifford Anderson of my staff. (FTS 488-1376)

Original Signed by
S. D. Ebner



Thomas T. Martin, Director
Division of Engineering and
Technical Programs

Attachment: As stated
ccc
cc w/attachment:
H. Haughey, NRR
D. Lazevnick, NRR
C. Anderson, RI
B. Gramm, RI

8310050072XA

F/5 62

OFFICE	MP	G/A	gm	SD		
SURNAME	PLISCO	ANDERSON	MARTIN	EBNER		
DATE	9/7/83	9/7/83	jr	9/8/83		