Weber

SES

SOIL ENGINEERS & SCIENTISTS, INC.

19366 ALLEN ROAD . TRENTON, MICHIGAN 48183

TELEPHONE. (313) 479-2444

FAX. (313) 479-4441

March 14, 1994

Mr. John A. Grobe, Chief Nuclear Materials Inspection Section 2 U.S. Nuclear Regulatory Commission Region III 801 Warrenville Road Lisle, Illinois 60532-4351

Re: Reply to a Notice of Violation License 21-26066-01 Docket 030-31333 EA 93-221

Dear Mr. Grobe:

Please consider this letter as a response to your letter dated March 7, 1994, in which two additional violations were listed. The following is a list of the violations and the corresponding corrective actions:

1. Violation:

Leakage/Contamination Tests for the Troxler were made

at intervals exceeding six months.

Reason for Violation:

Leak tests were the responsibility of an employee who left the company and did not transfer his responsibility to another employee, and the RSO did not provide sufficient follow-up to assure that the tests were done as required.

Corrective Steps:

Leak tests were immediately made for the moisture-

density gauges. No leakage was detected.

Long-term

Corrective Step:

RSO took immediate responsibility for conducting the leak tests instead of delegating responsibilities to another

employee.

Date Full-Compliance

Achieved:

August 19, 1993

2. Violation:

Failure to prepare and use proper shipping papers for

transporting moisture-density gauges to and from

construction sites.

Reason for Violation:

Unfamiliarity with the DOT requirements.

Corrective Steps:

Prepare new shipping papers that comply with DOT

requirements.

Long-term

Corrective Step:

Conduct regular meetings with the Troxler users to

remind them, along with other safety procedures, to carry

"proper" shipping papers at all times.

Date Full-Compliance

Achieved:

August 19, 1993

If you have any questions, please do not hesitate to call.

Very truly yours,

SOIL ENGINEERS AND SCIENTISTS, INC.

By:

Ed Al-Saati, P.E.

ED all-shaets

RSO

EAS:jeh