LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 1 L Q A D 1 2 0 0 0 - 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T REPORT L 6 0 5 0 0 0 2 5 4 7 0 8 2 4 8 2 8 0 9 0 7 8 2 9
0 2 0 0 August 24, 1982, at 0500 hours, the 1-ic71-65A Residual Heat Removal System (RHRS)
Service Water Pump was removed from service to repack (preventative maintenance)
0 4 the 1-1001-188A RHR room cooler isolation valve. Leakage from the isolation valve
o 5 did not affect the operation of the RHR Service Water Pump. All surveillances, as
o 6 required by Technical Specification 4.5.B.2 were successfully performed prior to
1 the removal of the 1-1001-65A pump. This RHRS Service Water Pump is one of two
100% redundant pumps, thus there were no safety implications associated with this occurrence cause cause cause
CODE SUBCODE S
TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE COMPONENT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER 1 0 7 5 20 36 37 40 41 43 42 43 44 44 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) 1 10 1 The IA RHRS Service Water Pump was removed from service to perform preventative
maintenance on an associated room cooler isolation valve. Following the completion
of this mainter ance, the IA RHRS Service Water Pump was returned to service by
1600 hours the same day. The pump was not tested for operability since no maintenance was performed which would have
affected is performance.
FACILITY STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 5 7 29 NA B 31 Operator Observation
ACTIVITY CONTENT 12 13 44 45 46 LOCATION OF RELEASE 36 80
1 6 Z 33 Z 34 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA 11 12 13
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA NA
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
PUBLICITY ISSUED DESCRIPTION 45
2 0 N 44 NA S20927 NA S0. 5 S0
PDR ADDCK 05000254 D. Jessen PHONE 309-654-2241, ext. 195