



ATTACHMENT TO

LER 82-074/03I-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

THE AUDIO MULTIPLIER WAS SET AT 1000 CPS. A SOURCE ASSEMBLY IN THE CORE WAS MOVED TO A LOCATION FURTHER AWAY FROM S.R. DET. N-31. THE 1000 CPS SETTING WAS TOO HIGH FOR THE NEW SOURCE LOCATION RESULTING IN TOO LONG A TIME INTERVAL BETWEEN SOUNDS. THE AUDIO COUNT RATE WAS LOWERED TO 100 CPS. RESTORING THE AUDIBLE INDICATION. FUTURE REFUELING PROCEDURES WILL INCLUDE A REQUIREMENT TO MAINTAIN THE AUDIBLE COUNT AT A DISTINGUISHABLE LEVEL.