

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39208

September 22, 1982

JAMES P. McGAUGHY, JR. ASSISTANT VICE PRESIDENT

> Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-13 File 0260/L-835.0

Omission of Smoke Detectors from Original Plant Design Reference: LER 82-060/01 T-0

AECM-82/417

On September 10, 1982, during an inspection by the Fire Protection Coordinator, two areas in the Auxiliary Building containing safety related cable were found to have no smoke detectors. Attached is LER 82-060/01 T-0, an interim report.

Yours truly,

John J. B. Mc Caughy J8.

JPM: 1m Attachment

cc: Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Document Control Desk (w/a) U.S. Nuclear Regulatory Commission Washington, D.C. 20555

TE 22