

13-26405-01

March 15, 1994

U.S. Nuclear regulatory Commission, Region III 801 Warrenville Road Lisle, Illinois 60532-4351

RE: Reply to a Notice of Violation

Gentlemen:

The reason the survey meter was not in an operable condition at the time of inspection was because the device was left in the "battery check" mode the last time it had been utilized, draining the energy source. Immediately following your inspection, the meter was sent away for servicing where upon new batteries were installed and the instrument was calibrated. It's now in an operable condition.

A check system has been developed in office so that more than one person will be present during a survey to ensure the meter will be turned off before storage.

Full compliance was achieved as of March 1, 1994.

Please feel free to contact me if you have any questions.

Sincerely, ATEC Associates, Inc.

Seen Miguel

Sean Miguel Field Operations Supervisor

SM/lkf

