LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 TOTAL SEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
REPORT LG 0 5 0 0 0 2 7 2 7 0 8 3 1 8 2 8 0 9 1 6 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 At 0930 hours, August 31, 1982, a service water leak was discovered on No. 12
O[3] Charging Pump lube oil cooler outlet piping. No. 12 Charging Pump was declared
o 4 inoperable, therefore, Action Statements 3.5.2a and 3.1.2.4 were entered at
0 5 0930 hours.
0 6
0 7
0 8 6
SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SU
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) 1 0 The cause was erosion of the piping by silt laden service water. The pipe was
replaced and the pump was tested satisfactorily. No. 12 Charging Pump was
declared operable and Action Statements 3.5.2a and 3.1.2.4 were terminated at 1722
hours. A Design Change Package has been submitted to replace the piping with a
more erosion resistant material.
7 8 9 FACILITY STATUS N POWER OTHER STATUS O
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 N/A LOCATION OF RELEASE 36 N/A N/A 44 45
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 8 9 PERSONNEL INJURIES PERSONNEL INJURIES 80
NUMBER DESCRIPTION 41 1 8 0 0 0 40 N/A
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A 8210010192 820916 PUBLICITY 45 NRC USE ONLY
ISSUED DESCRIPTION S DESCRIPTION S S S S S S S S S
NAME OF PREPARER R. Heller PHONE 609/935-6000 Ext. 3078