(7-77)	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 C 3 4 1 1 1 1 1 4 5 5.
CON'T	SOURCE LO 5 0 0 0 3 1 1 7 0 8 2 5 8 2 8 0 9 1 6 8 2 9 EVENT DATE 74 75 REPORT DATE 80
0 2	At 1053 hours, August 25, 1982, during surveillance testing, 2C Vital Bus Undervoltage
0 3	Relay failed to trip at the required setpoint. The channel was declared inoperable,
04	placed in a tripped condition, and Action Statement 3.3.2a Action 14 was entered at
0 5	1053 hours.
0 6	
0 7	
0 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	SH 11 X 12 Z 13 R E L A Y X 14 A 15 Z 6
	LER'RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. O 9 4 O 3 L O 3 L O 3 O 3 O 3 O 3 O 3
	ACTION FUTURE OFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUBMITTED SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUBMITTED SUBMITTED SUBMITTED SUPPLIER MANUFACTURER SUBMITTED SUBMITTED SUBMITTED SUBMITTED SUBMITTED SUPPLIER MANUFACTURER SUBMITTED SUBMITTED SUBMITTED SUPPLIER SU
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause was drift of the undervoltage relay trip setpoint. The setpoint was adjusted
1 0	
111	and tested satisfactorily. The channel was declared operable and Action Statement
1 2	3.3.2a Action 14 was terminated at 2032 hours, August 25, 1982.
1 3	
7 8	9
1 5	ACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 0 8 0 29 NA B 31 Surveillance Testing
	9 TIVITY CONTENT 12 13 44 45 46 LOCATION OF RELEASE 36 80
7 8	Z 33 Z 34 NA
17	NUMBER TYPE DESCRIPTION (39)
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 9	S 11 12 LOSS OF DR DAMAGE TO FACILITY 43 TYPE DESCRIPTION Z 42 NA
20	9 PUBLICITY SSUED DESCRIPTION 45 PDR ADDCK 05000311 S PDR DPR
	NAME OF PREPARER R. Heller PHONE: 609/935-6000 Ext 3078