

APPENDIX A
NOTICE OF VIOLATION

Carolina Power & Light Company
Harris Unit 1

Docket No. 50-400
License No. CPPR-158

As a result of the inspection conducted on June 20 - July 20, 1982 and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion XV as implemented by PSAR section 1.8.5.15, CP&L's Corporate QA Program section 5 and construction procedure CQC-2 require that nonconforming conditions be identified and corrected.

Contrary to the above, on June 30, 1982, two field welds on class IE electrical cable tray supports, that had been previously inspected by CP&L QC, were found to be nonconforming, and had not been documented as such, or corrected; in that one of the field welded joints on hanger item identified as 143G10, located in the reactor auxiliary building at elevation 261', was found to be undersized, and also at the same elevation, a fillet weld on hanger number ED2622 was found to be undersized. See the report details for further information on this matter.

This is a Severity Level IV Violation (Supplement II.D.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

AUG 04 1982

Date: _____