## LICENSEE EVENT REPORT

	EIGENGEE EVENT REPORT
٠.	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
0 1 7 8	REPORT LG 0 5 0 0 0 2 7 2 7 0 8 2 7 8 2 8 0 9 1 6 8 2 9
0 2	At 1600 hours, August 27, 1982, during surveillance testing of the 100' Elevation
0 3	Containment Air Lock, excessive leakage was discovered past the inner door seals.
0 4	The air lock was declared inoperable and Action Statement 3.6.1.3 was entered
G 5	at 1600 hours.
0 6	
0 7	
08	9
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	TO LERIRO EVENT YEAR SEQUENTIAL REPORT NO.  LERIRO EVENT YEAR SEQUENTIAL REPORT NO.  OCCURRENCE REPORT TYPE NO.  O 6 8
	ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER    H   18   F   19   Z   20   Z   21   0   0   0   0   Y   23   N   24   N   25   C   1   3   0   26
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	The seal was damaged by personnel closing the door with excessive force. The seal
11	was replaced and the surveillance test was satisfactorily performed. The air lock
1 2	was declared operable and Action Statement 3.6.1.3 was terminated at 2115 hours,
1 3	August 27, 1982. Design Change Requests have been submitted to install snubbers
1 4	on the doors.
1 5	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  E 28 0 3 5 29 N/A B 31 Surveillance Testing
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  Z (33) Z (34) N/A L N/A  9 10 11 44 45
1 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 0 0 0 (37) Z (38) N/A  9 PERSONNEL INJURIES 13 80
1 8	NUMBER O O O O O O O N/A
1 9	TYPE DESCRIPTION 43  N/A
20	PUBLICITY ISSUED DESCRIPTION 45  N/A  S  S  PDR ADDCK 05000272  PDR  NRC USE ONLY  PDR  NILITIAL SECONDARY  PDR  NOTE: The secondary of the se
6	NAME OF PREPARER R. Heller PHONE: 609/935-6000 Ext 3078