## LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 6.
O 1 7 8	REPORT L 6 0 5 0 0 0 3 1 1 7 0 9 1 0 8 2 8 0 9 1 6 8 2 9 5 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
0 2	At 0630 hours, September 10, 1982, a service water leak was discovered on No. 21
0 3	Containment Fan Coil Unit (CFCU). No. 21 CFCU was declared inoperable and Action
04	Statement 3.6.2.3a was entered at 0630 hours.
0 5	
0 6	
0 7	
7 8	80
0 9	SYSTEM CAUSE CODE SUBCODE SUBC
	LER'RO REPORT NUMBER 2 23 24 26 27 28 29 30 31 32
	ACTION FUTURE COMPCNENT SUBMITTED FORM SUB. PRIME COMP. COMPCNENT SUBMITTED FORM SUB. PRIME COMPCNENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER    X   Y   23   N   24   A   25   W   1   2   0   26
[1]0]	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)  The cause was erosion of the cooling coil. The leaking coil was blanked off and
111	No. 21 CFCU was satisfactorily tested. No. 21 CFCU was declared operable and Action
1 2	Statement 3.6.2.3a was terminated at 1650 hours, September 11, 1982. Design Change
1 3	Request 2EC-0505 has been submitted to replace the coils with a more erosion resistant
14	material.
1 5	ACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 31 Routine Surveillance
A	CIVITY CONTENT 12 13  LECASED OF RELEASE AMOUNT OF ACTIVITY 35  LOCATION OF RELEASE 36  NA 15 46  LOCATION OF RELEASE 36
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  O O 0 37 Z 38 NA
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41  O O O 0 40 NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  Z 42 NA
20,	PUBLICITY SSUED DESCRIPTION 45  PDR ADOCK 05000311 PDR ADOCK 05000311 S PDR ADOCK 05000311
	NAME OF PREPARER R. Heller PHONE: 609/935-6000 Ext 3078