## APPENDIX A

## NOTICE OF VIOLATION

Duke Power Company Oconee 2 Docket No. 50-270 License No. DPR-47

As a result of the inspection conducted on May 10 - June 10, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified.

A. Technical Specification 6.4.1. requires the station be operated in accordance with approved procedures for the normal startup of the complete facility and of all systems involving nuclear safety of the facility.

Contrary to the above, on May 19, 1982, the licensee failed to reset the main turbine trip contact buffers as required by step 3.2.112 of facility start-up procedure OP/2/A/1102/01 resulting in a reactor trip.

This is a Severity Level IV Violation (Supplement I.).

B. 10 CFR 50, Appendix B Criterion XVI as implemented by Duke Power Company Topical Report Duke-1A, section 17.2.16 requires the licensee to report and document conditions adverse to quality to appropriate levels of management.

Contrary to the above, on February 23, 1982 an operator neither reported nor documented that reactor building spray pump 1A had been run for approximately three hours with no flow which resulted in the destruction of the pump.

This is a Severity Level IV Violation (Supplement I.).

C. Technical Specification 6.4 requires written procedures with appropriate instructions to be provided for corrective maintenance which could affect safety.

Contrary to the above, Technical Specification 6.4 was not met in that on April 15, 1982, corrective maintenance was performed on safety-related valve 2HP-14 using a maintenance procedure that did not contain the appropriate instructions necessary to correctly reassemble the valve.

This is a Severity Level IV Violation (Supplement I.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will

Duke Power Company
Notice of Violation

Docket No. 50-270
License No. DPR-47

be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: JUL 1 2 1982