

Commonwealth Edison Zion Generating Station Shiloh Blvd. & Lake Michigan Zion, Illinois 60099 Telephone 312/746-2084

September 24, 1982

Mr. James G. Keppler Regional Director Office of Inspection and Enforcement Region III U.S. Nuclear Regulatory Commission Glen Ellyn, Illinois 60137

Reference: Zion Generating Station Docket No. 50-304/DPR-48 Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-304/82-21 for Zion Generating Station.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.(b).3 which states that observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems require a 30 day written report.

Very truly yours, K. L. Graesser

SEP 27 1982

TES

K. L. Graesser Superintendent Zion Station

KLG/ss cc: J. Waters

Enclosure: Reportable Occurrence Report No. 50-304/82-21

8210040116 820924 PDR ADDCK 05000304 5 PDR