	LICENSEE EVENT REPORT
	CONTROL BLOCK:
0 1	W I K N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT S8
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 0 5 7 0 8 2 5 8 2 8 0 9 2 4 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80  [While at full power operation, a damper on Train A of the Auxiliary Building Special ]
0 3	Ventilation System (ABSV) failed open (safe) causing the zone SV fan to start
0 4	[automatically. The system was taken out of service for corrective maintenance, placing]
0 5	the plant in a limiting condition of operation per T.S. 3.6.b.2. This event is
0 6	reportable per T.S. 6.9.2.b(2) as operation permitted by an LCO. The redundant train
0 7	was tested operable prior to removing the affected train from service, therefore, there
08	was no effect on public safety or plant operation.
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS   COURTING
; 0	A bad coil was replaced on the solenoid controlling the exhaust filter inlet damper.
11	The system was tested and placed back in service within T.S. limits. No further
12	action is required.
3	
	9 80
15	ACILITY STATUS OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32)  LE (23) L1 0 C (29) NA LA (31) 1A ABOV Exhaust Filter Damper Failed  OCTIVITY CONTENT 12 13 44 45 46 80
: 6	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  2 33 Z 34 NA  9 10 11  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY (35)  NA  44 45
1 7	NUMBER TYPE DESCRIPTION (39)  O O O O O O NA ON
· ŝ	O O O NA NA
, 9	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION
	PUBLICITY B210040159 B20924 ISSUED DESCRIPTION 45 PDR ADDCK 05000305 S PDR DR DESCRIPTION 45 PDR