LICENSEE EVENT REPORT

| LIGENSEE EVENT REPORT |
|--|
| CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) |
| 0 1 M D C C N 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 67 CAT 58 5 |
| CON'T O 1 |
| operations, pressurizer level deviated slightly from the program level |
| 0 4 by more than +/- 5% several times due to the loading of the Main Turbine |
| 0 5 Generator (T.S. 3.4.4). |
| 0 6 Similar events: 50-318/82-23 and 50-317/82-50. |
| 07 |
| 081 |
| SYSTEM CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD |
| RCS temperature swings of 10 degrees are not uncommon during normal |
| start-up operation. These temperature swings can result in deviations |
| of greater than +/- 5% from pressurizer program levels. Re-analysis |
| for justification of relaxation of Technical Specification is currently |
| 1 4 in progress. |
| The status of th |
| 7 8 9 10 11 44 45 80 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 0 0 0 (37) Z (38) N/A 7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) |
| 1 8 0 0 0 0 40 N/A 1 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 1 9 Z 42 N/A PUBLICITY OF ADOCK 05000318 PDR ADOCK 05000318 |