LICENSEE EVENT REPORT

CIOCHOCL EVENT REPORT
CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 C A S 0 S 2 2 0 0 - 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T 0 1 REPORT L 6 0 5 0 0 0 3 6 1 7 0 8 2 5 8 2 8 0 8 2 4 8 2 9 7 8 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 While in Mode 3, the condensate storage tank T-121 water level fell below the
[0]3 [Technical Specification 3.7.1.3 limit. There was no consequence to the public
0 4 health and safety since there was no significant decay heat in the core.
05
06
0 7
0 8 9
SYSTEM CAUSE CODE SUBCODE SUBC
TO REPORT NUMBER 2 23 24 26 27 28 29 30 31 32
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER SUPPLIER MANUFACTURER Z 9 9 9 9 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
Inadequate makeup water control to tank T-121 and a more restrictive than necessary
Technical Specification limit were the cause. Corrective actions include a proposed
Technical Specification change and a design change to install automatic level control
[1]3 systems (expected to be installed prior to 100% power operation).
1 4 L 7 8 9
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 A 31 Operator Observation
RELEASED OF RELEASE AMOUNT OF ACTIVITY 35
7 B 9 PERSONNEL INJUSTICE 13
1 3 O O O O O O NA
TYPE DESCRIPTION (43) NA 1 9 Z (2) NA NA
PUBLICITY 8210050024 820924 NRC USE ONLY PDR ADOCK 05000361 S PDR PDR PDR PDR
NAME OF PREPARER H. B. Ray 1 NUMBER 14/492-7700