## LICENSEE EVENT REPORT

-	CONTROL BLOCK: THE TASE PRINT OR TYPE ALL REQUIRED INFORMATION
0 1	T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 4 5 CAT SE
CON T	SOURCE L 6 0 5 10 10 10 13 12 17 0 0 19 10 13 18 12 3 0 19 13 10 18 12 3 0 19 13 10 18 12 3 0 19 13 10 18 12 3 0 19 13 10 18 12 3 0 19 13 10 18 12 3 0 18 12
0   2	With unit 1 in mode 1 (100% power) at 0720 CST on 09/03/82, one containment
0 3	pressure channel for the remote shutdown monitoring instrumentation was declared
0 4	inoperable due to failure to meet surveillance requirements. This event placed
0 5	the unit in action statement (a) of LCO 3.3.3.5. There was no effect upon public .
0 6	health or safety. Previous occurrences - none.
0 7	
[3]	
0 9	SYSTEM CODE CODE SUBCODE SUBCO
	LERIRO EVENT YEAR  SEQUENTI REPORT NO.  17 REPORT NO.  18 2
	ACTION FUTURE COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER M
10	During performance of SI-123, Maintenance personnel found the sense line isolation
111	valve to the pressure transmitter closed. A review on maintenance history records shows;   that the valve was verified to be open on 03/10/82 with no further maintenance performed.
100	
112	Therefore, the cause for the closed root valve is unknown. The isolation valve was
1 4	opened and the loop verified to be operable at 0930 CST on 09/03/82.
1 5	STATUS SPOWER OTHER STATUS (30) NA DISCOVERY DESCRIPTION (32)  B (31) Surveillance testing
	ELEASED OF RELEASE    Z   33   Z   34   NA   NA   NA   NA   NA   NA   NA   N
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 30 NA  1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
18	PERSONNEL INJURIES NUMBER OESCRIPTION (1) NA  NA  NA
[]]	TYPE DESCRIPTION (43)  Z 42 NA
20	PURLICITY ISSUED DESCRIPTION 45 PDR ADDCK 05000327 PDR ADDCK 05000327 PDR DESCRIPTION 45 PDR
	Name of Preparer: H. R. Rosers /M. R. Harding Phone: (615) 751-0349