

INTAT Precision, Inc.

State Road 3, North
P.O. Box 488
Rushville, Indiana 46173
(317) 932-5323
FAX NO. (317) 932-5323 Ext. 806
FAX NO. (317) 932-3032

DC D/DCB
INTAT

October 22, 1990

Mr. George M. McCann
Chief Nuclear Materials
Safety Section 1

License No. 13-23400-01

U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. McCann:

This is in response to your letter requesting a copy of our lockout Procedure in accordance with our license requirements. This procedure will be posted at the sight of the gauge and a copy kept by the maintenance department manager.

The Radiation Protection Officer (RPO) for INTAT is Gary Moore and the RPO alternate is Broderick Jenkins and Willie Oakes. These three are all maintenance department managers which give us twenty-four hour coverage at the foundry.

If you need further information please contact me by mail or phone (317) 932-5323, ext. 701.

Sincerely,

Mike Walker

Mike Walker
Safety Manager

rmw/clw
Enclosure

9011150008 901022
PEG3 LIC30
13-23400-01 PDC

DET 20 1990

IE07

Lockout Procedure for 3000 mCi Detector

Scope: To protect the team members of INTAT Precision, Inc., from exposure to radioactive material.

1. When access to the area between the source holder and the detector is required, the Radiation Protection Officer (RPO) or his designated alternate will be notified.
2. Upon notification of the need to access this area the RPO or his alternate will ensure the source holder is "off" and locked in the shielded position. He will place his own lock on the source holder at this time.
3. A radiation survey will be conducted to verify that the sources are shielded.
4. The source will remain locked "off" until it is verified that all work has been completed in this area and no further access is required.
5. The RPO or his alternate will remove his lock and return the source holder to the operating position only when the work is completed.
6. All team members, visitors, or contractors who require access to this area will be made cognizant of this requirement.
7. If the source holder itself needs work done on it, Ronan Engineering Company is contracted to do any repair or servicing.

Radiation Protection Officer

Gary Moore INTAT ext. 818
Home: 1-398-3063
Plant Engineer Manager

RPO Alternate

Broderick Jenkins INTAT ext. 817
Home: 938-2016
Maintenance Supervisor

RPO Alternate

Willie Oakes INTAT ext. 817
Home: No Phone
Maintenance Supervisor

Ronan Engineering Co.
(606) 342-8000