



Commonwealth Edison  
1400 Opus Place  
Downers Grove, Illinois 60515

April 12, 1994

Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Attention: Document Control Desk

Subject: Zion Station Units 1 and 2

Supplemental Response to NRC Bulletin 90-01  
Supplement 1 dated December 22, 1994

NRC Dockets 50-295 and 50-304

- References:
- 1) NRC Bulletin 90-01 Supplement 1, "Loss of Fill Oil in Transmitters Manufactured by Rosemount," dated December 22, 1992.
  - 2) D. J. Chrzanowski letter to Dr. T. E. Murley dated March 5, 1993.

Commonwealth Edison Zion Station's in our March 5, 1993 response (Reference 2) to NRC Bulletin 90-01 Supplement 1 (Reference 1) committed to NRC notification when two (2) high pressure, non-mature transmitters (2LT-461 and 1PT-405) have been replaced. These replacement was completed during the Winter 93/94 dual unit outage. This completes all requested Bulletin actions.

If there are any questions please contact me at (708) 663-7292.

Sincerely,

Martin J. Vonk  
Generic Issues Administrator  
Nuclear Regulatory Services

cc: J. Martin, Regional Administrator, NRC Region III  
C. Shiraki, Zion Project Manager, NRR/PDIII-2  
J. D. Smith, Senior Resident Inspector, Zion Station

k:\dave\zi9001.wpf\1

9404190183 940412  
PDR ADOCK 05000295  
Q PDR

JE39 1/0