

April 12, 1994

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Subject:

LaSalle County Station Units 1 and 2 Updated Final Safety Analysis Report (UFSAR) Facility Operating Licenses NPF-11 and NPF-18

NRC Docket Nos. 50-373 and 50-374

References

- (a) December 15, 1980 letter from D.G. Eisenhut (USNRC) to All Licensees
- (b) April 5, 1993 letter from M.B. Depuydt to U.S. Nuclear Regulatory Commission.
- (c) LaSalle Annual Report

Gentleme:1:

In accordance with the requirements of 10 CFR 50.71(e)(4), Commonwealth Edison submits Revision 10 to the Updated Final Safety Analysis Report (UFSAR) for the LaSalle County Station. Units 1 and 2 have a common FSAR and, therefore, this revision contains information for both units.

The UFSAR has been prepared in accordance with guidance approved by the May 9, 1980 Federal Register Notice 10 CFR 50.71(e) and Reference (a). Consistent with that guidance, this UFSAR revision has been retained in the original FSAR's format or content to conform with the recommendations contained in Regulatory Guide 1.70.

Commonwealth Edison has made every effort to identify all relevant information for this revision including modifications to the facility as described in the UFSAR that have been made since the last rubmittal (Reference (b)). In our judgement, the UFSAR accurately reflects the as-built condition of the plant as of October 17, 1993. All changes requiring NRC approval have been reviewed by the NRC (Reference (c)) and all others have safety evaluations on site to document the station's determination that prior approval was not required. Attachment A identifies the changes made under the provisions of 10 CFR 50.59 that were not previously submitted to the NRC, and provides a brief summary of these changes.

210003

A053

To the best of my knowledge and belief the statements contained in the UFSAR are true and correct. In some respects these statements are not based on my personal knowledge but upon information furnished by Commonwealth Edison employees. Such information has been reviewed in accordance with Company practice and I believe it to be reliable.

In accordance with the requirements of 10 CFR 50.4(b)(6), one signed original and ten (10) additional copies of the UFSAR revisions are provided. Also, attached is an "Index of Changes" which explains which pages of the UFSAR must be removed and which revised pages must be inserted.

Respectfully,

Gary Benes

Nuclear Licensing Administrator

Attachments

SUBSCRIBED AND SWORN to

before me this

day

24

1994

Notary Public

OFFICIAL BEAL
LYNN BLLEN GASSMAN
NOTARY PUBLIC STATE OF ILLINOIS
MY COMMISSION EXPIRES 1-24-97

cc: J.B. Martin - RIII w/o attachment

A.T. Gody, Jr. - Project Manager NRR w/o attachment

D.E. Hills - Senior Resident Inspector - LSCS w/o attachment

LAP-400-4 Revision 8 February 3, 1994

# ATTACHMENT B

# LASALLE COUNTY STATION UPDATED FINAL SAFETY ANALYSIS REPORT(UFSAR)TRANSMITTAL

TO ALL LASALLE UF	SAR HOLDERS:	April 17, 1994	10	
		Effective Date	Rev	ision
UFSAR. INSERT the	e new pages a	es from your controll s indicated. Sign th w. Return this signe	is transmittal	form in the
Admin Lasal 2601 I	. G. Trager istration Dep le Nuclear St North 21st Ro illes, IL 61	ation ad		
If you have Coordinator at ext	any question tension 2925.	s or comments, please	D. J. Ray Station Mans	ager
NOT THE THE THE THE THE THE THE THE THE TH		and and and also and any and and any and any one and any one and any one part and any one and and	LaSalle Cou	nty Station
1-12				
SET NO.		HOLDER SIGNATURE		DATE

The following is a summary of changes to the facility which are described in the Safety Analysis Report, made under the provisions of 10 CFR 50.59, not previously submitted to the NRC:

## UFSAR Volume V

Chapter 6 - Engineered Safety Features Revision to Section 6.3.2.2.6 to revise the required net positive suction head (NPSH) of the emergency core cooling pumps. This affected on calculations associated with station blackout analysis.

### UFSAR Volume VI

Chapter 7 - Instrumentation and Controls Administrative change to Section 7.3.6.2 to reflect the asbuilt configuration of the facility. Modifications M01-0-90-001, M01-1-90-001, M01-1-90-002, and M01-2-90-002 included crankcase gauge additions to diesel generators (DGs) 0, 1A, 1B, and 2B. This change clarifies that the gauges are for crankcase pressure indication (as opposed to crankcase vacuum).

# UFSAR Volume VI

Chapter 8 - Electric Power
Revision to UFSAR Section 8.3, to reflect a trip delay time band of 0.1 to 4.0 seconds in the Reactor Protection System (RPS) Electrical Protection Assembly (EPA) Trip Delay Time Requirements. EPA overvoltage, undervoltage, and underfrequency setpoints as specified in Technical Specifications are incorporated.

### UFSAR Volume VII

Chapter 9 - Auxiliary Systems Revision to UFSAR Section 9.5.4.4 to reflect Technical Specification amendments for Unit 1 and 2 associated with Diesel Generator fuel oil testing standards.

## UFSAR Volume VIII

Chapter 13 - Conduct of Operations Revision to UFSAR Chapter 13, Section 1 to reflect the relocation of the description of the station and corporate organizations to QA Topical Report CE-1-A, and its parent document, the Commonwealth Edison Company Quality Assurance Manual.

#### UFSAR Volume VIII

Chapter 15 - Accident Analysis Section 15.9, "Loss of All Alternating Current Power (Station Blackout)", added to UFSAR to address station blackout.

# UFSAR Volume VIII

Chapter 15 - Accident Analysis
Removal of Cycle Specific Information from the UFSAR that is
already included in the reload license package of each unit.
This eliminates redundancy of effort and reduces the
associated administrative burden.

UFSAR Volume IX

Appendix H - Fire Hazards Analysis
Update to UFSAR Appendix H, Section 3
Sections H.3.7.1, H.3.7.2, H.3.7.3 and H.3.8.2 (For fire zones 7A1, 7A2, 7A3 and 8A2 respectively) of the UFSAR indicated that the floor slabs of these fire areas are three (3) hour rated except for an oversized exhaust stack penetration. These sections are revised to clarify that the exhaust stack penetrations are unrated because of their size. This is consistent with the wording currently indicated in UFSAR section H.3.8.1 (for fire zone 8A1).

UFSAR sections H.3.7.4, H.3.7.5, H.3.7.6, H.3.8.3 and H.3.8.4 (for fire zones 7B1, 7B2, 7B3, 8B1, and 8B2, respectively) indicated that the ceiling of the rooms are three (3) hour rated except for an oversized exhaust stack penetration. These sections are revised to clarify that the exhaust stack penetrations are unrated because of their size. This is consistent with the wording indicated in UFSAR section H.3.8.1 (for fire zone 8A1). Additionally, UFSAR sections H.3.7.4 (for fire zone 7B1) and H.3.8.3 (for fire zone 8B1) are being revised to indicate which fire zones are located directly above them.