



LEAR REGULATORY COMMISS REGION II 101 MARIETTA STREET, N.W. ATLANTA, GEORGIA 30323

Report Nos.: 50-338/94-06 and 50-339/94-06

Licensee: Virginia Electric and Power Company

Glen Allen, VA 23060

Docket Nos.: 50-338 and 50-339

License Nos.: NPF-4 and NPF-7

Facility Name: North Anna 1 and 2

Inspection Conducted: March 14-18, 1994

Inspector:

Walter W. Stansberry

Date Signed

Date Signed

Approved by: Dox 46.

D. R. McGuire, Chief Safeguards Section

Nuclear Material Safety and Safeguards Branch Division of Radiation Safety and Safeguards

SUMMARY

## Scope:

This routine, announced inspection was conducted in the areas of Physical Security Program for Power Reactors and Protection of Safeguards Information. Specific areas evaluated were: Security Program Plans; Protected and Vital Area's Physical Barriers, Detection Aids and Assessment Aids; Protected and Vital Area Access Control; Alarm Stations and Communications; Power Supply; Testing, Maintenance and Compensatory Measures; Protection of Safeguards Information; and Security Training and Qualification.

## Results:

In the areas inspected, two violations were identified. One violation of regulatory requirements relating to the failure to provide adequate protection for safeguards information, identified and reported by the licensee was confirmed. This is a repeat violation (see Paragraph 3). The other violation was related to the misissuance of a personnel access control badge (see Paragraph 2e). This violation satisfied the criteria in Section VII.B. of the NRC Enforcement Policy and consequently will be a noncited violation.

- Failure to issue appropriate personnel access control badge (noncited violation No. 94-06-01).
- Failure to mark, control and provide adequate protection for safeguards information (repeat Violation No. 92-06-02).

SAFEGUARDS INFORMATION

## SAFEGUARDS INFORMATION

2

Otherwise, the licensee continues to provide appropriate security for the vital resources of this facility. Review, observation and evaluation of the security operational activities confirmed that the management and operational effectiveness of the security organization was maintained as documented in previous inspection reports.