



October 6, 1982
L-82-432

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2
Docket No. 50-389, 50.55(e), 82-014
VALVES WILL NOT RESPOND TO COMMAND SIGNALS

On June 30, 1982, Florida Power and Light Co. (FPL) notified Region II Office of Inspection and Enforcement, in accordance with the requirements of 10 CFR 50.55(e) of a potential deficiency regarding the failure of reactor shutdown cooling bypass valves to respond to command signals. FPL is still reviewing this problem and will submit a final report by October 30, 1982.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Robert E. Uhrig".

Robert E. Uhrig
Vice President
Advanced Systems and Technology

REU/jea

cc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

82 OCT 12 AID: 98
USNRC-REGION II
ATLANTA, GEORGIA