Attachment to AECM-82/484

	Page 1 of 1
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 s	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 5 26 LICENSE TYPE 30 57 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 0 9 1 6 8 2 8 1 0 1 8 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  During the performance of the Containment Cooling Pre-Operational Test, it was noted
0 3	that the Containment Ventilation Monitoring System Effluent Flowrate Monitor (Table
0 4	3.3.7.12-1) failed to give proper indication. T.S.3.3.7.12 requires this flow monitor
0 5	to be fully operable at all times. This is being reported per the requirements of
06	T.S.6.9.1.13.b. The event did not result in any significant occurrence, release of
0 7	radioactivity or have any affect upon public health or safety.
0 8	9 80
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	17 REPORT 8 2 0 8 1 0 3 L 0 3 30 31 32 ACTION FUTURE FEECT SHUTDOWN ATTACHMENT NPPD-4 PRIME COMP. COMPONENT
	TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER [X] [8] [X] [9] [2] [2] [0] [0] [0] [0] [N] [23] [N] [24] [A] [25] [A] [1] [8] [26]
10	The cause of the flow monitor failing to give proper indication is believed to be a
111	clogged flow sensor. A maintenance work order has been issued to remove, insepct and
1 2	clean the flow sensor. This is an Interim Report; an updated LER will be issued when
1 3	final resolution is known.
1 4	
7 8	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  G 28 0 0 0 0 29 NA  A 31 Pre-Operational Test  80  A 31 Pre-Operational Test
	CONTENT CONTENT AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 NA
177	PERSONNEL EXPOSURES NUMBER O 0 0 0 37 Z 38 NA  NA  NA
18	PERSONNEL INJURIES NUMBER DESCRIPTION 41  NA  NA  NA
1 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  NA  NA
7 8	9 10 8210220289 821018 NRC USE ONLY 9 PDR ADOCK 05000416
2 0	PDR ADOCK 05000418 PDR NA  S PDR NA  68 69 80 5
	NAME OF PREPARER Original signed by W. H. Chenault PHONE: