

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority
Sequoyah 1 and 2

Docket Nos. 50-327 & 50-328
License Nos. DPR-77 & DPR-79

As a result of the inspection conducted on August 16-20, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 6.8.1.a requires that the licensee establish, implement, and maintain written procedures covering the control of radioactivity. Gaseous Effluent Requirements Procedure No. SI-415, Section 2.2, Inoperable Monitors, requires that the noble gas activity release rate be recorded on TI-37 log sheet B.35.

Contrary to the above, on July 27, 1982, noble gas release rates were not recorded on TI-37 log sheet B.35 for all effluent radiation monitors that were declared inoperable due to power failure of an electrical panel.

This is a Severity Level V Violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: September 3, 1982