



Carolina Power & Light Company

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429

October 15, 1982

FILE: B09-13510C  
SERIAL: BSEP/82-2259

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 3100  
101 Marietta Street N.W.  
Atlanta, GA 30303

USNRC REGION II  
ATLANTA, GEORGIA  
92 OCT 21 9 52

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1  
LICENSE NO. DPR-71  
DOCKET NO. 50-325  
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8a

Dear Mr. O'Reilly:

In our letter of May 18, 1982 (Serial No. BSEP/82-1073), concerning fire dampers, a commitment was made to perform an inspection to ensure all plant safety-related ventilation duct fire dampers are installed as required. While performing this inspection, it was discovered that a ventilation duct located at penetration seal DG-2-034 on the 23-foot elevation of the Diesel Generator Building did not have an inspection door to permit a determination of the required fire damper's existence within the duct. As a result, the subject penetration seal was then declared inoperable and the associated LCO and hourly fire watch patrol were generated in accordance with technical specifications.

In order to determine the required fire damper's existence, plant Engineering has been requested for assistance in providing an inspection access to the damper.

Very truly yours,

C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

RMP/mcg/LETGG

cc: Mr. R. C. DeYoung

8210260294 821015  
PDR ADOCK 05000325  
S PDR

OFFICIAL COPY  
TE 22