LICENSEE EVENT REPORT

Elocitoce e rent lier out
CONTROL BLOCK: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
F L S L S 1 2 0 0 - 0 0 0 0 - 0 0
SOURCE L GO 5 0 010 13 3 5 0 0 19 2 3 8 2 3 1 0 1 5 8 2 3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
[0]] CEAs was found deleted making the pulse counting position indication !
required by TS 3.1.3.3 inoperable. The pulse counting function was
[3]5] [immediately restored. This function is controlled by the plant process
[0] computer. There was no affect on public health and safety. This is one of
[0] several position indication systems. There have been indication losses
[0]3 before but this is the first due to this cause.
SYSTEM CAUSE SUSCODE S
17 KEPORT L 8 2 1 22 22 24 76 27 28 29 30 31 32
TAKEN ACTION ON PLANT SHUTTON NOUNS ACTION ON PLANT SHUTTON ACTION ON PARTICIPATION ACTION ACTIO
[1] When correcting differences in actual and pulse counter indicated CEA
positions a procedure step was missed and the counting function was left
disabled. Methods of alerting the operator that pulse counting is out of
service are being investigated (for example, adding an alarm).
STATUS SPONER OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) [1] 5 E (3) 0 9 9 NA B (3) Operator Observation
7 2 2 1G 13 13 44 45 45 45 45 45 45 45 45 45 45 45 45
TIS Z TO NA
VUMBER DESCRIPTION (29) NA
7 3 3 25 25 20 20 21 13 23 23 24 25 25 25 25 25 25 25 25 25 25 25 25 25
NA NA
TOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA
PLACICTY SECTION DESCRIPTION (45) NAC USE CALY
NA I I I I I I I I I I I I I I I I I I I
NAME OF PREPARE P. L. Pace 240NE (305) 552-3654