

Certified By

*MAL***YANKEE ATOMIC ELECTRIC COMPANY**

Rowe, Massachusetts 01367

October 13, 1982

United States Nuclear Regulatory Agency
 Office of Inspection and Enforcement
 Region I
 King of Prussia, Pa. 19406

Attn: Mr. R. C. Haynes

Dear Mr. Haynes:

Pursuant to the requirements of Technical Specifications, Section 6.9.4.a(2) the following is reported as Licensee Event Report 50-29/82-35 01T.

As stated in the telephone report made on 10/13/82, the reactor protection system permissive bistables, B/S 420 and B/S 423 were found to be calibrated out of tolerance due to a surveillance procedure inadequacy. The bistables were calibrated to actuate the permissive circuit slightly above or below the required ≤ 15 mweg or ≥ 15 mweg.

A more detailed report will follow in 14 days.

Very truly yours,

Herbert A. Antio
 Plant Superintendent

HAA /
 meg

8210260428 821013
 PDR ADOCK 05000029
 S PDR

IE 29