

RR No. 2, Box 3270 Wiscasset, Maine 04578 207-882-6321

October 18, 1982

MN-82-203

United States Nuclear Regulatory Commission Directorate of Regulatory Operations Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference: License No. DPR-36 (Docket No. 50-309)

Dear Sir:

Subject: Maine Yankee Reportable Occurrence #82-30/01T-0

Pursuant to the requirements of Technical Specification 5.9.1.6.I, the Maine Yankee Atomic Power Company hereby submits the following report.

Maine Yankee has been informed by its Engineering Support Group that one of the pipe supports in the Primary Component Cooling System may not meet design criteria. The plant was in the Refueling Shut lown condition at the time of discovery. No further immediate corrective action is considered necessary.

Maine Yankee intends to pursue confirmation and final resolution of this problem prior to plant startup.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

Edwin C. Wood.

Edwin C. Wood Plant Manager

ECW/vl