NRC Form 591 . U.S. NUCLEAR REGULATORY COMMISSION 12-81 10 CFR 2.201 SAFETY INSPECTION 2. REGIONAL OFFICE SUPERIOR ASPHALT CO. INC. 11030 HICKMAN MILLS DR. U.S. NUCLEAR R'GULATORY COMMISSION REGION III KANSAS COTY, MO 64126 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137 5. DATE OF INSPECTION 24-26/62-01 030-31561 NOV. 2,1990 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commissions (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows: 1. Within the scope of this inspection, no violations were observed. 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time. 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements. THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11. was not properly posted to indicate the presence _. 10 CFR 20.203(b), (c), (d), (e) or 34.42. were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2), of realed sources were not performed at the proper frequencies. 10 CFR License Condition Number ____ D. Records of ... were not properly maintained. or License Condition Number 10 CFR E. Documents were not properly posted or otherwise made available. 10 CFR 19.11. F. Reports or notifications of ___ or License Condition Number with 10 CFR TAH FAILURE TO PROPERLY DISTLAY/STORE SHIPPING PAPERS DURING TRANSPORT OF RADIOACTIVE MATERIAL. 49 CER 177. 817 (e); locazilis. FAILURE TO SECULE RADIOACTIVE MATERIAL DURING TRANSPORT TO PREVENT SHIFTING, 49 CFR 173, 448(a) AND 49 CFR 1842(d) AND hereby state that within 30 days the aclions described by me to the inspector will be taken to correct the violations ide itified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response vill be submitted unless required by the NRC. 9012180086 901115 REG3 LIC30 24-26162-01 PDF PDR SIGNATURE - LICENSEE

NRC Form 59.1	AND THE RESIDENCE OF THE PARTY	THE CONTRACTOR OF THE PARTY OF	U.S. NUCLEAR REGULATORY COMMISSION
SAFETY INSPECTION Ded /De B			
SUPERIOR ASPHALT CO INC. SUPERIOR ASPHALT CO INC. 11030 HICKMAN MILLS DR. P. & BOX 9669 KANSAS CITY, MO 64126		U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137	
3. DOCKET NUMBER(S) 4. LICENSE "LUMBER(S) 7.4. 7.4.7.7.4.7.7.4.7.7.		-01	6. DATE OF INSPECTION
030-31561 24-26/62			NOV. 2,1990
The inspection was an examination of the activities conducted under your license as they relate to			
Cof sealed sources were not performed at the proper frequencies. 12 OFRLicense Condition Number			
D. Records of			
F. Reports or notifications of			
with 10 CFR or License Condition Number			
			AL DURING PANSFORT (A) ANTI 49 CFR 71.5
			the viol cions identified in the items checked above further response will be sub-nitted unless required by Loger 11-9-90 RE-NRC INSPECTOR DATE

17 000

MOV 2 3 1898