

H. B. ROBINSON STEAM ELECTRIC PLANT Post Office Box 790 Hartsville, South Carolina 29550

## OCT 2 2 1982

Robinson File No: 13510C

Mr. James P. O'Reilly Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

> H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2 DOCKET NO. 50-261 LICENSE NO. DPR-23 LICENSEE EVENT UPDATE REPORT 81-31, REVISION 1

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit No. 2, the enclosed Licensee Event Report is submitted. The original report, dated December 15, 1981, described the failure of the Pressurizer Power Operated Relief Valve Block Valves to close during a plant transient on November 30, 1981. The enclosed update report describes the original event and provides the results of investigational efforts and corrective actions which have been taken. This new information is indicated by a vertical bar in the right margin. This report, therefore, supersedes and should replace all copies of the original LER.

Very truly yours,


R. B. Starkey, Dr.

General Manager H. B. Robinson S. E. Plant

HTC:pb

Enclosure

cc: R. C. DeYoung (40) R. A. Hartfield (3)



EOFFICIAL CONT

22

OCT

28

w

SERIAL:RSEP482-1225