

### LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | S | G | G | S | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 1 | 6 | 7 | 0 | 9 | 2 | 3 | 8 | 2 | 8 | 1 | 0 | 2 | 3 | 8 | 2 | 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
0 2 | During shutdown, smoke detectors in zones 2-06, 2-07, 2-17, and 2-20 of the Auxiliary |  
0 3 | Building alarmed and would not clear. No fire or smoke was present. The alarms were |  
0 4 | deactivated. There was no effect on the health and safety of the public and did not |  
0 5 | constitute a threat to plant safety. |  
0 6 | \_\_\_\_\_ |  
0 7 | \_\_\_\_\_ |  
0 8 | \_\_\_\_\_ |

0 9 | A | B | 11 | C | 12 | Z | 13 | I | N | S | T | R | U | 14 | E | 15 | Z | 16 |  
7 8 9 10 11 12 13 18 19 20  
17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | - | 23 | 0 | 7 | 6 | 24 | 26 | / | 27 | 0 | 3 | 28 | 29 | L | 30 | - | 31 | 0 | 32 |  
18 | ACTION TAKEN | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | N | 24 | A | 25 | H | 2 | 6 | 0 | 26 |  
33 34 35 36 37 40 41 42 43 44 47  
EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 23 24 26 OCCURRENCE CODE 28 29 REPORT TYPE 30 31 REVISION NO. 32  
ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 40 ATTACHMENT SUBMITTED 41 NPD-4 FORM SUB. 42 PRIME COMP. SUPPLIER 43 COMPONENT MANUFACTURER 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 0 | An LCO was entered and an hourly fire watch established for each zone in |  
1 1 | accordance with T.S.3.3.7.9. The smoke detectors failed in an alarmed condition due |  
1 2 | to dust accumulation. The detectors were cleaned and returned to operable status. |  
1 3 | The LCO was lifted on September 29, 1982. This is being submitted as a final report. |  
1 4 | \_\_\_\_\_ |

1 5 | B | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | Alarmed Condition | 32 |  
7 8 9 10 12 13 44 45 46 80  
1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36 |  
7 8 9 10 11 44 45 80  
1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 |  
7 8 9 10 11 12 13 80  
1 8 | 0 | 0 | 0 | 40 | NA | 41 |  
7 8 9 10 11 12 80  
1 9 | Z | 42 | NA | 43 |  
7 8 9 10 80  
2 0 | N | 44 | NA | 45 |  
7 8 9 10 80  
FACILITY STATUS 28 % POWER 29 OTHER STATUS 30 METHOD OF DISCOVERY 31 DISCOVERY DESCRIPTION 32  
ACTIVITY CONTENT 33 RELEASED OF RELEASE 34 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
PERSONNEL EXPOSURES 37 NUMBER 38 TYPE 39 DESCRIPTION  
PERSONNEL INJURIES 40 NUMBER 41 DESCRIPTION  
LOSS OF OR DAMAGE TO FACILITY 42 TYPE 43 DESCRIPTION  
PUBLICITY 44 ISSUED 45 DESCRIPTION  
NRC USE ONLY  
8210290135 821023  
PDR ADOCK 05000416  
S PDR  
78 79 80

NAME OF PREPARER Original signed by John M. Albert

PHONE \_\_\_\_\_