

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-409/82-16(DETP)

Docket No. 50-409

License No. DPR-45

Safeguards Group: IV

Licensee: Dairyland Power Cooperative
2615 East Avenue - South
La Crosse, WI 54601

Facility Name: La Crosse Boiling Water Reactor (LACBWR)

Inspection At: LACBWR Site, Genoa, WI

Inspection Conducted: September 20-24, 1982

Date of Last Physical Security Inspection: August 3-5, 1981

Type of Inspection: Routine, Unannounced, Physical Protection

Inspector: Gary S. Pirtle
G. L. Pirtle
Physical Security Specialist

10/20/82

Approved By: J. R. Creed
J. R. Creed, Chief
Safeguards Section

10/20/82

Inspection Summary

Inspection on September 20-24, 1982 (Report No. 50-409/82-16(DETP))

Areas Inspected: Included a review of Site Orientation; Security Plan and Implementing Procedures; Security Organization - Management - Personnel - Response; Security Program Audit; Records and Reports; Testing and Maintenance; Locks, Keys, and Combinations; Physical Barriers - Protected Area - Vital Areas; Security System Power Supply; Lighting; Assessment Aids; Access Control - Personnel - Packages; Detection Aids - Protected Area; Alarm Stations; Personnel Training and Qualification Plan; Safeguards Contingency Plan; Licensee's Action on Previous Inspection Findings; Followup on Unresolved Items; and Independent Inspection. The inspection involved 41 inspector-hours onsite by one NRC inspector. The inspection began during the day shift period; six inspection-hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined during this inspection except for the following two items:

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled

1. Testing and Maintenance: A test of security equipment was not completed in accordance with the licensee's test procedures (Paragraph 13.a).
2. Alarm Stations: A piece of security equipment was not alarm equipped as required by the licensee's security plan (Paragraph 23.a).

Security concerns noted in the previous inspection were closed. One unresolved item was closed. An unresolved item pertaining to tamper alarms for certain equipment will be sent to NRC Headquarters for resolution. The licensee committed to analyze the lighting in certain locations and include some security management changes in appropriate security plans.

(Details - SAFEGUARDS INFORMATION)

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Declassified