# U. S. NUCLEAR REGULATORY COMMISSION Region I

| Report No.<br>Docket No.<br>License No. | 50-352/82-11<br>50-353/82-08<br>50-352<br>50-353<br>CPPR-106<br>CPPR-107 | Priority       |              | Category | 13          |
|---|--|----------------|--------------|----------|-------------|
| Licensee:                               | Philadelphia Electric Co.  |                |              |          |             |
|   | 2301 Market Street   |                |              |          |             |
|   | Philadelphia, Pa. 19101  |                |              |          |             |
| Facility Name:                          | ne: Limerick Generating Station, Units 1 & 2                             |                |              |          |             |
| Inspection at: Limerick, Pa.            |  |                |              |          |             |
| Inspection cond                         | ducted: August   | : 16 - Septemb | er 17, 1982  |          |             |
| Inspector:                              | Be McCole, for<br>S. K. Chaudhary, Sr. Resident Inspector                |                |              |          | date signed |
| Approved By:                            | E. C. McCabe,  |                | ts Section 2 | ĒB       | date signed |

Inspection Summary:

# Inspection on August 16 - September 17, 1982 (Report 50-352/82-11 and 50-353/82-08)

Areas Inspected: Routine on-site resident inspection (64 hr., Unit 1; 1 hr., Unit 2) of electrical cable pulling, housekeeping, welding, and small-bore pipe supports.

Results: No violations or deviations were identified.

### DETAILS

#### 1. Persons Contacted

#### Philadelphia Electric Co.

- D. Clochey, QA Engineer
- \*J. Corcoran, Field QA Branch Head.
- F. Coyle, QA Engineer
- G. Lauderback, QA Engineer

## Bechtel

M. Jan Assistant Project Field Engineer K. Stout Project Field QCE

Other engineering and craft personnel were contacted during the inspection.

\*Attended the exit meeting.

#### 2. General Walk-Through Inspection

The inspector, during walk-through inspection, specifically examined licensee practices in the areas of electrical cable pulling, small-box pipe supports, and the welding of supports in the suppression chamber.

The inspector observed that the electricians performing cable pulling were using proper tools, the cable was properly tagged, and protection was applied to cables to prevent damage. No small bore pipe support deficiencies were found, but the specific supports the inspector examined had not been finally inspected and accepted by Quality Control. For the suppression pool piping and down-comers, the inspector found that welding operations were carried out in accordance with good practices.

No violations were identified.

#### 3. Exit Interview

The inspector periodically discussed the findings of his inspection with the licensee staff. A final exit interview was conducted by telephone on September 17, 1982. The inspection scope and the findings were discussed with Mr. J. Corcoran, the licensee's field QA Branch Head.