LICENSEE EVENT REPORT
CONTROL BLOCK:
0 1 M A Y K R 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 57 CAT 68
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) REPORT L G O S O O O O Z 9 7 O 9 Z 4 8 Z 8 1 O Z Z 8 Z 9
[0]3 [No. 2 Battery and Charger Replacement", the battery rooms' halon system]
[0]4 [was removed from service to facilitate installation of a new battery
charger for No. 2 battery. The system is required to be operable by T.S.
[0] [3.7.10.5. An hourly fire watch patrol with backup suppression equipment]
was maintained during the 28.5 hour outage period. There was no adverse
effect to the public health or safety as a result of this occurrence.
SYSTEM CAUSE COMPONENT CODE COMPONENT CODE SUBCODE SUB
The cause of this occurrence was the need to relocate some of the halon
[1] system equipment in order to install a new battery charger for No. 2
station battery. The halon system equipment was manufactured by the
Pyrotronics Company. The necessary equipment was relocated and system
returned to service. No further corrective action is necessary.
7 8 9 FACILITY STATUS \$ POWER OTHER STATUS OTHER STATUS
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 7 8 9 10 11 PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 N/A 44 45 LOCATION OF RELEASE 36
1 7 0 0 0 37 Z 38 DESCRIPTION (39) N/A PERSONNEL INJURIES 13 80
1 8 0 0 0 40 DESCRIPTION (41) N/A
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A N/A
7 8 9 10 PUBLICITY PDR ADDCK 05000029 N/A S PDR ADDCK 05000029 PDR 68 69 NRC USE ONLY
NAME OF PREPARER Edwin L. May PHONE (413) 625-6140