Bulletin Reply 79-14

REGION VISE

Docket No. 50-397

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

October 19, 1982 G02-82-858

Docket No. 50-397

Mr. R. H. Engelken, Director Office of Inspection and Enforcement Nuclear Regulatory Commission Region V 1450 Maria Lane Suite 210 Walnut Creek, California 94596

Subject:

NUCLEAR PROJECT NO. 2 IE BULLETIN 79-14

Reference:

Letter, GO2-79-156, DL Renberger to RH Engelken,

subject, "WPPSS Nuclear Project No. 2, IE Bulletin 79-14"

dated September 7, 1979

The following clarification is submitted to the reference in regard to our response to the subject bulletin.

The reference stated in part that as-built drawings are given additional checks by contractors' QA/QC inspectors on all safety-related piping and supports, and that the process is controlled by project procedures and is monitored by the Owner's QA group who perform random surveillances. Due to evolutionary changes in construction practices, as-built drawings are given additional checks by contractor field engineers rather than QA/QC inspectors on all safety-related piping and supports. Contractor QC inspectors do perform the in-process inspections to insure that construction is performed in conformance with the approved design. As before, this process is controlled by project procedures, and is monitored by the Owner's QA group who perform random surveillances.

R. G. Matlock

Program Director, WNP-2

RGM: CJF:cph

cc: Mr. R. Auluck - NRC

Mr. W. S. Chin - BPA Mr. R. Feil - NRC Site