

LICENSEE EVENT REPORT

CINTULA

CONTROL BLOCK: 0136181121 161 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCCN1 200-000000-000 3411111 410 5

CON'T 01 REPORT SOURCE L6 05000317 70401181 8043081 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 At 1910 on April 1, 1981, while conducting normal operations, Baltimore
03 Gas and Electric Company received notification that several supports in
04 #12 SRW Subsystem did not meet interim acceptance criteria of an estab-
05 lished program developed in response to IE Bulletin 79-14. (T.S. 3.7.
06 4.1). The supports were modified and the subsystem returned to service
07 on April 15, 1981, at 0430. #11 subsystem remained in service through-
08 out this event.

09 SYSTEM CODE W A 11 CAUSE CODE B 12 CAUSE SUBCODE A 13 COMPONENT CODE S U P P O R T I 14 COMP SUBCODE A 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 8 11 18 ACTION TAKEN F 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER B 1 3 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 The on-going detailed analysis of all supports for piping systems en-
11 compassed by IE Bulletin 79-14, discovered inadequate pipe supports
12 installed in #12 SRW for Unit 1. The hangers found to be unacceptable
13 were redesigned and modified/replaced, as required.

14
15 FACILITY STATUS E 28 % POWER 1 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY D 31 DISCOVERY DESCRIPTION Informed by AE 32
16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

NAME OF PREPARER L. L. Weckbaugh

PHONE (301) 263-4719

8211020563 810430
PDR ADOCK 05000317
S PDR

NRC USE ONLY
60522

80 81 7-826

C36812

LER NO. 81-29/3L  
DOCKET NO. 50-317  
LICENSE NO. DPR-53  
EVENT DATE 04-01-81  
REPORT DATE 04-30-81  
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

The Architect Engineer for the project is continuing its effort to identify any questionable or unacceptable supports through detailed analysis.