LICENSEE EVENT REPORT
CONTROL BLOCK:
0 1 C A R S S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58 5
**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (1) While performing surveillance test SP 206.03A, on September 23, 1982, the
[0]3 A Emergency Diesel failed to start on "AC" starting air. The Diesel was
[0]4] then started on the "DC" starting air to confirm operability. There were
o o ransients, nor was public or plant safety affected by this event.
0 6
0 7
SYSTEM CAUSE CODE SUBCODE SUBC
TO REPORT 8 2
Some oil-like substance was found in the air relay valve and the air motor
[1] [oil reservoir was discovered to be empty. The valves were cleaned, the
reservoir was filled, and the system was start-tested and found satisfactory.
During the next refueling outage, this system will be examined again.
7 8 9
FACILITY STATUS OTHER STATUS OTHER STATUS ODISCOVERY DESCRIPTION ODISCOVERY DESCRIPT
7 8 ACTIVITY CONTENT 12 13 44 45 46 LOCATION OF RELEASE 36 N/A N/A N/A 10 11 11 44 45 46
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 N/A PERSONNEL INJURIES N/A
1 8 0 0 0 40 N/A
1 1 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION N/A N/A
PUBLICITY OESCRIPTION 45 2 0 Y 44 Local newspapers and wire services. NRC USE ONLY 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
NAME OF PREPAREE R. W. Colombo PHONE: (916) 452-3211