-81) CFR 2:201	SAFETY IN	ISPECTION	Delle B
BFGoodrich, Adhesive Systems Division 123 W Bartges Street D/1931 B/2768 Akron OH 44311		U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137	
DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION
030-30833	34-09024-07		December 20, 1990
gulatory Commission's (NRC) rules and regulation of representative records, interviews, with person 1. Within the scope of this inspection, no viols 2. The inspector also verified the steps you had those actions at this time.	ons and the conditions of younel, and observations by the ations were observed. Ive taken to correct the violations were observed. It taken to correct the violations were observed. It is seen to correct the violations were observed below, were on its required to be posted in	ur license. The inspect inspector. The finding tions identified during in violation of NRC reaccordance with 10 C	the last inspection. We have no further questions on equirements.
B. Containers located in			. 10 CFR 20.203(b), (c), (d), (e) or 34.42
	oactive material, 10 CFR 20).203(f)(1), or (f)(2).	was not properly posted to indicate the presence

SIGNATURE - LICENSEE 9101020042 901220 REG3 LIC30 34-09024-07 PDR

12/20/20 VO