

APPENDIX A
NOTICE OF VIOLATION

Arkansas Power and Light Company
Arkansas Nuclear One, Units 1 and 2

Dockets: 50-313/82-28
50-368/82-26
Licenses: DPR-51
NPF-6

Based on the results of an NRC inspection conducted during the period of September 1-30, 1982, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987, dated March 9, 1982, the following violations were identified:

1. Failure to Adhere to the Requirements of the Operations Training Program - Units 1 and 2

Criterion V of 10 CFR Part 50, Appendix B, states that activities affecting quality shall be prescribed by documented instructions or procedures and shall be accomplished in accordance with these instructions or procedures.

Licensee Procedure 1023.08 requires that licensed operators shall review the abnormal and emergency operating procedures not less than twice each year. This procedure also requires the maintenance of a requalification status log, containing specified minimum information.

Contrary to the above:

- . One licensed operator had not completed and documented a review of abnormal and emergency operating procedures for Unit 1 in 17 months and for Unit 2 in 18 months. (313/8228-02; 368/8226-02)
- . Requalification status logs, containing the minimum specified information, were not being maintained to monitor the progress of licensed personnel during the annual requalification training cycle. (313/8228-01; 368/8226-01)

This is a Severity Level V Violation. (Supplement I.E)

2. Failure to Adhere to Requirements of Refueling Shuffle Procedure - Unit 2

Unit 2 Technical Specification 6.8.1 requires that, "Written procedures shall be established, implemented, and maintained covering ... a. The applicable procedures recommended in Appendix 'A' Regulatory Guide 1.33."

Refueling and Pre-op Sequence of Events Procedure 2502.01, Rev. 2, "Refueling Shuffle," has been established in accordance with this Technical Specification.

Section 6.27 of Procedure 2502.01 states that the following minimum personnel are required to carry out fuel handling operations when transferring fuel to/from the auxiliary building:

- . One control room operator
- . One spent fuel bridge operator
- . One fuel handling area upender operator
- . One reactor fuel bridge operator
- . One reactor building upender operator
- . One senior reactor operator in charge

Contrary to the above, on September 10, 1982, the licensee failed to station either a fuel handling area upender operator or a reactor building upender operator while transferring fuel to the auxiliary building. (368/8226-05)

This is a Severity Level V Violation. (Supplement I.E)

Pursuant to the provisions of 10 CFR 2.201, Arkansas Power and Light Company is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated: October 18, 1982