



Maine Yankee Reportable Occurrence 82-032/03L-0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES CONTINUED

exchanger to perform its intended safety function. The SCC system is closed and normally provides no direct release path. The Primary Component Cooled E-3A RHR heat exchanger was not affected. Continued sampling of SCC while on RHR during refueling shows no further evidence of leakage. There was no impact on the health and safety of the public.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS CONTINUED

further evidence of a leak.

The procedure for surveillance sampling of SCC and PCC shall be revised to require a sample within 24 hours of placing the heat exchangers within the RHR mode.