

October 29, 1982

Mr. James G. Keppler
Regional Director
Office of Inspection and Enforcement
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station

Docket No. 50-295/DPR-39

Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/82-33 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 10/26/82 and by telegram/mailgram on 10/26/82.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a(5) which states that failure or malfunction of one or more components which prevents or could prevent, by itself, the functional requirements of system(3) used to cope with accidents analyzed in the SAR require a 14 day written report.

Very truly yours,

K. L. Graesser Superintendent

Zion Station

cc: J. Waters

Enclosure: Reportable Occurrence Report No. 50-295/82-33

8211060305 821029 PDR ADDCK 05000295 S PDR

1822