



Northern States Power Company

414 Nicoliet Mall Minneapolis, Minnesota 55401-1927 Telephone (612) 330-5500

December 28, 1990

10 CFR Part 50 Section 50.73

U S Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

> PRAIRIE ISLAND NUCLEAR GENERATING PLANT Docket Nos. 50-282 License Nos. DPR-42 50-306 DPR-60

Discovery That Certain Valves Should Be Subject to ASME Section XI Testing Found through Design Basis Reconstitution

The Licensee Event Report for this occurrence is attached.

Please contact us if you require additional information related to this event.

for Thomas M Parker
Manager
Nuclear Support Services

c: Regional Administrator - Region III, NRC NRR Project Manager, NRC Senior Resident Inspector, NRC MPCA

Attm: Dr J W Ferman

Attachment

1

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INECPMATION COLLECTION REQUEST SOO HAS FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECERCIS AND REPORTS MANAGEMENT BRANCH (#530), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON DC 10555, AND TO THE PAPERWORK REDUCTION PROJECT 12150-0164. OFFICE OF MANAGEMENT AND BUDGET WASHINGTON DC 10563.

										St. meuen	DATE OF THE PARTY						
FACILITY				A CALL COMMON CONTRACTOR OF THE PARTY OF THE		-	ALCOHOLD STATE		Control of the last of the las	-	CKET NUMBER			PAGE	(3)		
											151010	012	1812	1 OF	0 2		
TITLE (4)	Dis	cover	y The	t Certain	Valves	Shou	ld Be	a Subj	ect to	ASME					-		
	Sec	tion	XI Te	sting Fou	nd throu	igh I	esign	n Basi	s Reco	nstitutio	0						
EVENT DATE (5) LER NUMBER (6)					REPORT DATE (7) 0				OTHER F	HER FACILITIES INVOLVED IN							
MONTH	UAY	YEAR	YEAR SEQUENTIAL NUMBER		REVERN	MONTH	DAY		FACILITY MAMES			DOCKET NUMBER(S)					
-									Prairi	e Island	Unit 2	0 5	1010	10131	0 16		
1 1	3 0	9 0	10	0 1 8	- 0 0	1 2	2 8	9 10				0 5	10 10	1011			
0.00	RATING	Maria Indiana in America	THITRE	ORT IS SUBMITTE	D FUREUANT T	D THE R	LOUIREN	ENTE OF	10 CFR 4: 10	hack one or more of	the lastermay) (1	11					
MODE (B)			20.4	20.402(b)			29.406(4) 80.73(a)(2)(iv			50.72(a)(2)(iv)			73.71(e)				
	ROWER			26.406(4)(1)())				50.36(a)(1) 50.73(a)(2)				ei 73			73,71(e)		
LEVEL	1	1 0 0 26.408(4)(1)(8) 50.28(4)(2) 60.73(4)(2)						50.73(a)(2)(9H)	(VIII) OTHER (Sparity in Abs								
20.406(4)(1)(iii)				OB (a) (1) (iii)	XX	XX 50.73(4)(2)(1) 50.73(4)(2)					1(e(k) (%)			356A1			
			20.4	50,73(a)(21(iii) 50,73(a)(21(iii)) 50,73(a)(21(iii)) 50,73(a)(21(iii))			50,73(a)(2)(*iki)(8										
			20				50.73(6)(2)(8)										
		economica la s		-		ICENSES	CONTAC	T FOR TH	S LER (12)	-		75. 75	ONE NUM	410			
NAME											AREA CODE	TELEPHONE NUMBER					
Ar	ne A	Huns	tad						THE RESERVE AND ADDRESS OF THE PERSON OF THE		6,1,2	3 8	181-	111	2 11		
		-		COMPLETE	ONE LINE FOR	EACH C	DHPONE	NT FAILUR	E DESCRISE	D IN THIS REPORT	F-1121	-					
CAUSE	SYSTEM	COMP	PONENT	MANUFAG. TURER	MEPORTABLE TO NPROS			CAUS	E SYSTEM	COMPONENT	MANUFAC. TURER		DATABLE NAROS				
	es yanitations	-	-		-	1	-	0.00		Bernard Street Street							
	1	1	1 1	111						131.1							
*****	h	obstance desca		SUPPLEM Majorita	ENTAL REPORT	EXPECT	180 (14)	and the same of	and replace Architect		EXPEC	750	MONT	H DAY	YEAR		
VV1	8 /// www	entra a se de	. x > 4 C 7 5 D	SUBMISSION DAT	T)	-	ОМ				SUBMIS	NOIL	0 12	014	911		

AASTRACT (Limit to 1400 spaces i.e. approximately lifteen single-space typewritten sines 1161

On November 30, 1990, both units were at 100% power. A review of the design bases for Gooling Water System revealed that certain cooling water and chilled water valves required to mitigate the consequences of an accident are not included in the Prairie Island ASME Section XI inservice testing program. The valves in question were cycled during motor operated valve periodic maintenance and surveillance testing, but this testing did not satisfy the testing requirements of Section XI; that is, valve timing was not performed or trended, and the test was not done often enough. However, the testing is considered satisfactory to verify that the valves had been operable.

The investigation of this event is not yet complete because conflicting information exists regarding the safety functions of these valves. Resolution of those conflicts is expected shortly, at which time a supplemental report will be submitted.

These valves have all subsequently been cycled to obtain baseline data for their inclusion in the ASME Section XI inservice testing program. No abnormal parameters were observed. Additional corrective actions will be discussed in the supplemental report.

NRS FORM 386A

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED DMB ND. 3150-0104 EXPIRES: 4/30/93

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 500 HRS. FORWARD COMMENTS REQUENTED HE STIMATE TO THE RECORD AND REPORTS MANAGEMENT BRANCH (P.530). U.S. NUCLEAR REQUESTORY COMMISSION WASHINGTON DC 2065S. AND TO THE PAPERWORK REDUCTION PROJECT (3)500-104. OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	FAGE 131					
		YEAR SCOVENTIAL REVISION NUMBER						
Prairie Island Unit 1	0 5 0 0 0 2 8 2	9 0 - 0 1 8 - 0 0	0 2 0 9 2					

TEXT IN more appear in required, you Additional NRC Form 3864's/ (17)

DESCRIPTION

On November 30, 1990, both units were at 100% power. A review of the design bases for Cooling Water System revealed that certain cooling water and chilled water valves required to mitigate the consequences of an accident are not included in the Prairie Island ASME Section XI inservice testing program.

ASME Section XI requires pt. odic exercising of all valves required to mitigate the consequences of an accident. The valves in question were cycled during motor operated valve periodic maintenance and surveillance testing, but this testing did not satisfy the testing requirements of Section XI; that is, valve timing was not performed or trended, and the test was not done often enough. However, the testing is considered satisfactory to verify that the valves had been operable.

The investigation of this event is not yet complete because conflicting information exists regarding the safety functions of these valves. Resolution of those conflicts is expected shortly, at which time a supplemental report will be submitted.

CAUSE OF THE EVENT

Cause of the event will be discussed in the supplemental report.

ANALYSIS OF THE EVENT

This event is reportable pursuant to 10CFR50.73(a)(2)(i)(B) since Technical Specification 4.2.A.2 was violated.

CORRECTIVE ACTION

These valves have all subsequently been cycled to obtain baseline data for their inclusion in the ASME Section XI inservice testing program. No abnormal parameters were observed.

Additional corrective actions will be discussed in the supplemental report.

FAILED COMPONENT IDENTIFICATION

None.

PREVIOUS SIMILAR EVENTS

There have been no previous similar events reported at Prairie Island.