LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M A P P S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58 6
REPORT L 6 0 5 0 - 10 2 9 3 7 0 9 3 0 8 2 8 1 0 2 9 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 O 2 On 9/30/82, at steady state conditions, at 75% power, an alarm was received for low
old nitrogen pressure in CRD 22-51 accumulator. After recharging, the alarm was again
0 4 received. Power was reduced to 55%, the rod fully inserted, rod pattern adjusted,
o 5 and the accumulator taken out of service in accordance with T.S. 3.3.D. This
0 6 event caused no threat to the public health and safety.
07
7 8 9
SYSTEM CODE CODE SUBCODE SUBCO
1 0 A leaking accumulator was the cause of this event. The unit was replaced with a
spare, rebuilt accumulator and the drive successfully tested per procedure 9.9.
The drive was placed back in service on 10/3/82 at 1433. The removed accumulator
was then rebuilt to be used as a spare. General Electric supplied the Accumulator
(EP#125) as part of the CRD hydraulic control unit. (HCU)
FACILITY STATUS THER STATUS TO METHOD OF DISCOVERY DESCRIPTION (32) [1 5 E (28) 0 7 5 (29) NA A (31) Operational Event
7 8 9 10 10 12 13 44 45 46 46 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA NA NA NA NA
2 8 9 10 11 44 45
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA NA
NUMBER TYPE DESCRIPTION (39) 1 7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 1 8 0 0 0 0 (40) NA
NUMBER TYPE DESCRIPTION (39) NA NA PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA NA LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION (43)
NUMBER TYPE DESCRIPTION (39) NA PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA NA NA 1 8 9 11 12 80 NA 1 9 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION . NA
NUMBER TYPE DESCRIPTION (39) NA PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA NA 1 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION . NA.